TEMPORARY PAVEMENT RESTORATION

FIGURE 7-6

NOT TO SCALE