

Title: HMA Plant - Aggregate Storage and Handling	Pennsylvania Asphalt Improvement Network	Document No.:QPM007-01	Effective Date: 20-Dec-06 Rev: 00	Page: 1 of 3
Owner/Approver:	Reviewed By:	Reviewed By:	Reviewed By:	Reviewed By:

1.0 PURPOSE:

This procedure describes the storage and handling methods of aggregate and Reclaimed Asphalt Pavement (RAP) at Hot Mix Asphalt (HMA) plant operations to ensure that aggregate and rap are mixed to customer specifications.

2.0 SCOPE:

This procedure applies to the storage and handling of all incoming aggregate and RAP at the HMA plant.

3.0 RESPONSIBILITY:

HMA plant management and operating personnel.


4.0 EQUIPMENT NEEDED:

Front End Loader and Automated Conveyor systems.

Notice: This hardcopy document must be used for reference purpose only. The user is responsible for assuring that it is the same as the current document revision level shown online.

Title: HMA Plant - Aggregate Storage and Handling	Pennsylvania Asphalt Improvement Network	Document No.:QPM007-01	Effective Date: 20-Dec-06 Rev: 00	Page: 2 of 3
Owner/Approver:	Reviewed By:	Reviewed By:	Reviewed By:	Reviewed By:

5.0 **PROCEDURE:**



Notice: This hardcopy document must be used for reference purpose only. The user is responsible for assuring that it is the same as the current document revision level shown online.

Title: HMA Plant - Aggregate Storage and Handling	Pennsylvania Asphalt Improvement Network	Document No.:QPM007-01	Effective Date: 20-Dec-06 Rev: 00	Page: 3 of 3
Owner/Approver:	Reviewed By:	Reviewed By:	Reviewed By:	Reviewed By:

6.0 Revision Log

<u>Revision</u>	<u>Date</u>	<u>Description</u>	<u>Requested By</u>	<u>Completed By</u>
00	20-Oct-06	Initial Release	<u>PASIN Core Team</u>	<u>MDL / FJC</u>

Notice: This hardcopy document must be used for reference purpose only. The user is responsible for assuring that it is the same as the current document revision level shown online.

P:\penndot shared\ISO-QMS Expansion Project in Construction\Asphalt ISO 9000-2000 Pilot Team\Quality Manual - Work File\PASIN QMS Procedure Sheets - HMA\QPM007-01 HMA Plant - Aggregate Storage and Handling 06-12-20 Rev-00.doc
Date Printed 12/20/2006