

**PENNDOT – Engineering District 10-0
ISO 9001 Internal Audit Report
(02/06)**

Department	Audit Process	Date & Time of Audit
PennDOT – Construction Unit	7.5.3 Identification and Traceability	TBD

Auditor(s)	Audit Objectives:
1. Anthony Brinklow 2. Terry Lezanic	Review process to insure compliance and improve effectiveness with ISO 9001:2008 and organization requirements.

Name of Auditee(s)	Auditee(s) job Function
1. Paul Koza	1. ADE Construction

Item(s) or areas audited
Review of measurement, analysis and improvement

Auditee Comments:
None

<u>Plan approved by: (Management Representative)</u>

PENNDOT – Engineering District 10-0 ISO 9001 Internal Audit Report

Audit Criteria
<p data-bbox="256 302 737 338"><u>External</u> requirements (questions)</p> <p data-bbox="277 369 354 401">1. N/A</p>
<p data-bbox="256 581 717 617"><u>External</u> requirements (answers)</p>
<p data-bbox="256 966 725 1001"><u>Internal</u> requirements (questions)</p> <p data-bbox="305 1033 397 1064">1. N/A</p>
<p data-bbox="256 1268 708 1304"><u>Internal</u> requirements (answers)</p> <p data-bbox="277 1314 298 1346">1.</p>

PENNDOT – Engineering District 10-0 ISO 9001 Internal Audit Report

Overall Statement of Effectiveness of the Quality Management System

Areas of strength regarding ability to meet requirements- including observed BEST Practices

1. Based on project documentation and audit results the process appears to be working efficiently.

Areas to consider for improvement:

1. None observed.

Specific observed nonconformities (Findings): If Applicable, Follow-up Scheduled:

1. None.

Observations and auditor comments:

1. Consider the elimination of this process.

Statement of overall effectiveness of the system:

- Appears to be good, however; difficult to measure.

Distribution of Audit Report:

- Manager of area audited
- A.D.E. Construction
- ISO Management Representative

Unit Manager Comments Including Follow-Up Action: (if any)

